

Výškoměry | Height Gauges | Wysokościomierze

Výškoměr analogový

Height Gauge

Wysokościomierz suwmiarkowy

0,02



CODE	
3014-02-020	0 - 200 mm
3014-02-030	0 - 300 mm
3014-02-050	0 - 500 mm
3014-02-100 	0 - 1000 mm