



OPERATION INSTRUCTION

Welding Gage


Code 4840-1




使用说明书

4840-1 焊接规


Graduation	Accuracy
0.2mm	$\pm 0.1\text{mm}$




Measuring purpose




分度值	精度
0.2mm	$\pm 0.1\text{mm}$




测量方法:



Reading: A means scale A, B means scale B, C means scale C



读数: 图示尺寸A、B、C分别对应刻度A、刻度B、刻度C读数



MN-4840-C/E

V0

MN-4840-C/E

V0