



Morse Taper Adapter with Tang



Size	MT.No.	L	D
NT30-MTA1-50	1	50	25
NT30-MTA2-50	2	50	32
NT30-MTA3-75	3	75	40
NT40-MTA1-50(OTT)	1	50	25
NT40-MTA2-50(OTT)	2	50	32
NT40-MTA3-65(OTT)	3	65	40
NT40-MTA4-95(OTT)	4	95	48
NT50-MTA1-45(OTT)	1	45	25
NT50-MTA2-60(OTT)	2	60	32
NT50-MTA3-65(OTT)	3	65	40
NT50-MTA4-70(OTT)	4	70	48
NT50-MTA5-105(OTT)	5	105	63