











# Quick Setting Vise



## Features

- Special design for quick clamping. (From the acme thread shaft stationly)
- Quick setting by sliding movement. Big clamping capability.
- Operating very quick and easy, can increase so much working efficiency than you can image.
- Good for short term and massive production or proto type work.
- Suit for milling machine, grinder machine, precision drilling machine using.
- Accurate grounded and assembled.
- Precision cut acme thread, it can get 800kgs high clamping force.
- Horizontal & vertical
- Accuracy 0.02 / 100 mm



| ORDER NO. | A   | B  | C max. | D  | E   | E1  | F  | G | H  | I  | I1  | J   | K   | M  | MAX.Clamp Force kgf | G.W. | CODE NO. |
|-----------|-----|----|--------|----|-----|-----|----|---|----|----|-----|-----|-----|----|---------------------|------|----------|
| VQS-3     | 81  | 34 | 85     | 36 | 230 | 374 | 12 | 5 | 70 | 51 | 128 | 82  | 230 | 50 | 700                 | 7    | 1002-262 |
| VQS-4     | 105 | 36 | 104    | 36 | 256 | 422 | 12 | 5 | 72 | 54 | 148 | 106 | 256 | 54 | 800                 | 9.5  | 1002-263 |
| VQS-5     | 131 | 36 | 125    | 38 | 297 | 490 | 13 | 5 | 74 | 59 | 178 | 132 | 297 | 67 | 800                 | 14.5 | 1002-264 |