## BAER Machine Taps Set M 3 - M 12 for stainless steel

HSSE Machine Taps for through hole incl. HSSE/Co Extreme drill bits for core holes



through holes up to 4 x D



chip removal (like picture)



Form B with spiral point



4-5 threads



IS02/6H

## **Set Content**

 BAER HSSE Stainless steel
 M 3 x 0,5 | M 4 x 0,7 | M 5 x 0,8

 Machine Taps
 M 6 x 1,0 | M 8 x 1,25 | M 10 x 1,5

 through hole
 M 12 x 1,75

 BAER HSSE/Co
 2,5 mm | 3,3 mm | 4,2 mm | 5,0 mm |

 Extreme drill bits for core holes
 6,8 mm | 8,5 mm | 10,2 mm

