

Accelerometer PCE-VT 3700S



Handy entry-level device for vibration monitoring of machines and systems / HOLD function / Peak value measurement / Handheld device for mobile vibration measurement / Automatic ISO 10816-3 evaluation

The accelerometeris ideal for maintenance workers to quickly check vibrating parts, machines and systems. This vibration meter shows the vibration acceleration, vibration velocity and vibration displacement directly on the display. You can use the device to quickly and reliably detect machine imbalances which can lead to, for example, bearing damage. The vibration meter is equipped with a mode that allows a measurement according to ISO 10816-3 to be carried out. The vibration meter analyzes the measured values and automatically shows a good / bad evaluation on the display.

The vibration meter is supplied with a sensor on the spiral cable, magnet adapter, service bag and batteries. The display of the vibration meter is a colored graphic display, which makes operation easier, since all instructions and menu items are shown in plain text. The 12 languages in the menu of the vibration meter are easily switchable.

- Automatic ISO 10816-3 evaluation
- Easy to handle
- For mobile vibration measurement
- -The measurement unit can be switched between the metric system and imperial units.
- Colored graphic display
- Peak-hold function





www.pce-instruments.com

Specifications

Acceleration

1 kHz - 10 kHz

10 Hz - 10 kHz

±2 %

Velocity

±2 %

±2 %

10 Hz - 1 kHz

Displacement

1 μm / 39.4 μin

10 Hz - 200 Hz

Crest factor

2.4" LC display

RMS, Peak, Peak-Peak

switchable metric / imperial

English, German, French

Portuguese, Turkish, Polish

Spanish, Italian, Dutch

0.1 m/s² / 3.94 in/s²

0.0 - 399.9 m/s² / 0.0 - 15744 in/s²

0.00 - 399.99 mm/s / 0.00 - 15.74 in/s

0.000 - 3.999 mm / 0.000 - 0.154 in

0.01 mm/s / 0.0039 in/s

Measuring range

Resolution Accuracy @ 160 Hz Frequency range

Measuring range

Resolution Accuracy @ 160 Hz Frequency range

Measuring range

Resolution Accuracy @ 160 Hz

Frequency range

Measurement parameters

Units Display

Menu languages

Russian, Chinese, JapanesePower supply3 x 1.5 V AA batteriesOperating and storage conditions-20 ... +65 °C / -4 ... 149 °F; 10 ... 95 % r.H.Dimensions150 x 80 x 38 mm / 5.9 x 3.1 x 1.5"Weight170 g / 6 oz

Technical Data Vibration Sensor

Resonance frequency	24 kHz
Transverse sensitivity	≤ 5%
Destruction limit	5000 g (peak)
Operating and storage temperature	-55 +150 °C / -67 302 °F

More information



Housing material	stainless steel and plastic
Mounting thread	1⁄4 - 28"
Dimensions	Ø 29 x 81 mm / 1.14 x 3.18"
Weight (without cable)	119 g / 4.2 oz

Subject to change



www.pce-instruments.com