

PCE Americas Inc.
711 Commerce Way
Suite 8
Jupiter
FL-33458
USA
From outside US: +1
Tel: (561) 320-9162
Fax: (561) 320-9176
info@pce-americas.com

PCE Instruments UK Ltd.
Units 12/13
Southpoint Business Park
Ensign way
Hampshire / Southampton
United Kingdom, SO31 4RF
From outside UK: +44
Tel: (0) 2380 98703 0
Fax: (0) 2380 98703 9
info@pce-instruments.com

www.pce-instruments.com/english www.pce-instruments.com

## Technical Thermometer PCE-889B

Digital infrared thermometer for non-contact temperature measurement / Adjustable emissivity / Optical resolution 30:1 / Measuring range of -50 ... +1000 °C / Double laser aiming / Maximum value display

The digital infrared thermometer is suitable for private and industrial use because of its price-performance ratio. An infraredthermometer is a contactless measuring device. The bright laser dots from infrared instruments are clearly visible and provideeasier temperature measurement from a distance. The spot size ratio allows the user to make even the most remotemeasurements. The emissivity of the infrared thermometer is adjustable.

The temperature range that is measurable is between -50 and +1000 °C. Thus, a large area is covered and this is also the reason why the infrared thermometer is so versatile. The operational area of the infrared thermometer is quite large. This equipment can be used in many processes of industry, handicrafts, trade and hobbies. Thus, the infrared thermometer can be used for maintenance of manufacturing facilities. It also helps to ensure the cold chain, and is used for the temperature checking of workpieces.

- Optical resolution 30:1
- Measuring range of -50 ... +1000 °C
- Maximum value display
- Adjustable emissivity
- Double laser aiming
- Backlit display

## **Technical Data**

Measuring ranges -50 ... +1000 °C

Resolution 0.1 °C

Accuracy  $\pm 1 \%$ Response time <150 ms

Ratio of measuring distance to spot size 30:1

Adjustable emissivity, depending on the material 0.1 ... 1.0

Spectral range  $8 \dots 14 \mu m$ 

Visible laser beams for sighting

Double laser (class 2)

Dimensions

146 x 104 x 43 mm

Weight 163 g Temperature units  $^{\circ}\text{C}$  /  $^{\circ}\text{F}$ 

Display functions HOLD function, automatic shutdown,

maximum value display

Backlight yes

Indicator if temperature is exceeded yes

Duration measurement function yes

Alarm output yes

Power supply 9 V block battery

## **Delivery Contents**

- 1 x Digital Infrared Thermometer PCE-889B
- 1 x Battery
- 1 x Instruction manual