


## FEELER GAGE TAPES

| Code    | Thickness (T) | Accuracy |
|---------|---------------|----------|
| 4621-02 | 0.02mm        | ±4µm     |
| 4621-03 | 0.03mm        | ±4µm     |
| 4621-04 | 0.04mm        | ±4µm     |
| 4621-05 | 0.05mm        | ±4µm     |
| 4621-06 | 0.06mm        | ±4µm     |
| 4621-07 | 0.07mm        | ±5µm     |
| 4621-08 | 0.08mm        | ±5µm     |
| 4621-09 | 0.09mm        | ±5µm     |
| 4621-10 | 0.10mm        | ±5µm     |
| 4621-12 | 0.12mm        | ±5µm     |
| 4621-15 | 0.15mm        | ±6µm     |
| 4621-18 | 0.18mm        | ±7µm     |
| 4621-20 | 0.20mm        | ±8µm     |
| 4621-25 | 0.25mm        | ±9µm     |

| Code     | Thickness (T) | Accuracy |
|----------|---------------|----------|
| 4621-30  | 0.30mm        | ±9µm     |
| 4621-35  | 0.35mm        | ±11µm    |
| 4621-40  | 0.40mm        | ±12µm    |
| 4621-45  | 0.45mm        | ±12µm    |
| 4621-50  | 0.50mm        | ±14µm    |
| 4621-55  | 0.55mm        | ±14µm    |
| 4621-60  | 0.60mm        | ±14µm    |
| 4621-65  | 0.65mm        | ±14µm    |
| 4621-70  | 0.70mm        | ±17µm    |
| 4621-75  | 0.75mm        | ±17µm    |
| 4621-80  | 0.80mm        | ±19µm    |
| 4621-85  | 0.85mm        | ±19µm    |
| 4621-90  | 0.90mm        | ±22µm    |
| 4621-95  | 0.95mm        | ±22µm    |
| 4621-100 | 1.00mm        | ±24µm    |



4621-30



- Used as shims to accurately set spacing
- Made of hardened alloy steel
- Length 5m
- Width 13mm