

Dial Test Indicator K 37

These are instruments distinguished by high sensitivity and high demands are made for accurate measurements of concentricity and roundness in warrant easy, non-tiring use.

Standard equipment includes: 1 contact point with 2 mm diameter
1 spanner for changing the contact points.

Dial Test Indicator K 37	
Reading	0.002 mm
Range	0.2 mm
Dial reading	0-100-0
Bezel-Ø	32 mm
Form to DIN 2270	B
Dimensions and accuracy according to	DIN 2270
Measuring force	0.15 N ± 20%
Length of contact point	12.8 mm
Swivelling range of contact point parallel to the scale	240°
Dimensioned drawing	page 93

