

# MACHOS DE MÁQUINA


## TARAUDS MACHINE / MACHINE TAPS / MASCHINENGWINDEBOHRER

**2133**

**HSSE DIN 371**

**M**  
DIN 13

**B-AZ**




Tol.  
**6H**

**3XD**

**R**

P				M		K			N				S		H		
<800	<1.000	<1.200	<1.400	<950	<1.200	<500	<800	<1.400	Al	Cu	Mg/Zn	Plastic	Ni	Ti	50 HRC	55 HRC	60 HRC
									● 10-20	○ 6-8	○ 10-20	○ 10-15					

Vc (m/min). ● Optima / Optimun ○ Alternativo / Alternative



Ø	P
M3,0	0,50
M4,0	0,70
M5,0	0,80

L mm	l mm	mm	d mm
56	11	2,70	3,5
63	13	3,40	4,5
70	16	4,90	6,0

Ø	P
M6,0	1,00
M8,0	1,25
M10,0	1,50

L mm	l mm	mm	d mm
80	19	4,90	6,0
90	22	6,20	8,0
100	24	8,00	10,0